



Existing Home

Slope which may slump with additional channel widening.

Slope adjoining stream which appears to have slumped away due to past channel erosion (widening).

Stream